March 3, 2010 9:03:34 AM

Page 1

Work Order ID 56637

Item ID:

DSI 9410-011

Accept

Setup Start

Revision ID: Item Name:

Step Modification

Start Date: Required Date: 3/03/10

3/03/10

Start Qty: 1.00 Req'd Qty: 1.00

Cust Item ID:

Date:

Date:

Customer:

Reference:

Approvals:

Process Plan:

Date:

Date: Tooling:

Run

Start

Stop

Stop

Sequence ID/ **Work Center ID**

Operation Description Set Up/ **Run Hours**

SPC (Y/N):

Draw Number

Draw Rev.

Plan Code

Accept Qty Qty

Reject Reject Number

Insp. Stamp

Draw Nbr

Revision Nbr

QC:

DSI 9410

В

0.00

Document Control

Memo

0.00

Photocopy bluefile &type labels per PPP DSI 9410-011

CHG002

mc1 10/03/03

110

100

Packaging

Pick Kit

0.00

Memo

0.00

Packaging

120

QC

QC4- 100% Inspect kits for completeness

Memo

Quality Control

Work	Order	ID	56637

Page 2

March 3, 2010 9:03:35 AM

Item ID:

DSI 9410-011

Accept

Setup Start

Revision ID:

Item Name:

Step Modification

Start Date:

Required Date: 3/03/10

3/03/10

QC:

Start Qty: 1.00

Req'd Qty: 1.00



Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan:

Date:

Date: _____ Tooling:

SPC (Y/N):

0.00

0.00

Date:

Date:

Start Run

Qty

Stop

Stop

Sequence ID/ **Work Center ID**

Operation Description Set Up/ **Run Hours**

Draw Number

Draw Rev.

Plan Code

Accept Qty

Reject Reject Number

Insp. Stamp

130

Packaging Packaging

Memo

Identify and pack for shipping as per PPP DSI 9410-011

Location: PPP rev:

140

QC21- Final Inspection - Work Order Release

0.00

QC Quality Control Memo

0.00

N 10-03.03

Picklist Print

March 3. 2010 9:03:33 AM

Work Order ID: 56637

Parent Item:

DSI 9410-011

Parent Item Name:

Step Modification

Comments:

IPP RevA: New issue DD verified by:EC

10.03.03 verified by:EC

IPP rev:B as per dwg RevB DD

Start Date: 3/03/10

Required Date: 3/03/10

Start Otv: 1.00 Required Oty: 1.00

Component Item ID/ Item Name

AN4-15A

Item ID

Replacement Mfg/ Purch Purchased Bin Item No

No

No

No

Primary Location

Last Location

Route Seq ID 110

Unit of Measure Each

Oty on Hand 159.0000

Remaining Otv To Pick 8.0000

Otv Issued Date Issued

Status

Warehouse Loc Oty Loc Code Location Main Warehouse 159

ST

113121 113538

3 113840 150 110 Each

0.0000

0.0000

Loc Code

16.0000

M 113706 10-3-3 St

B43118 10-3-3 SV

Washer

Rubber Cushion

D3595

QS1 017

45/149/004631

Manufactured

Manufactured

Purchased

110

110

Each

sf

27,7000 0.0833

B39953 10.3.3

Rubber Cushion (per sq ft)

Warehouse Loc Qty Location Main Warehouse ST 27.7 31948 3.29 32894 6.63 33542 17.78

(D3595-200-300) Cut(2) at 2.00" X 3.00" as per dwg D3595 (per kit)

March 3, 2010 9:03:33 AM

Work Order ID: 56637

DSI 9410-011

Parent Item Name:

Step Modification

Comments:

Parent Item:

IPP RevA: New issue DD verified by:EC

10.03.03 verified by:EC

IPP rev:B as per dwg RevB DD

Start Date: 3/03/10

Start Qty: 1.00

Required Date: 3/03/10

Required Qty: 1.00

Date

Component Item ID/ Item Name MS21042L4

Replacement Mfg/ Item ID

Purch Purchased

Primary Item Location No

Last Location

Route Seq ID 110

Unit of Measure Hand Each

Qty on 1,821.000 8.0000

Remaining Qty **Qty To Pick**

Issued

Status Issued

Nut

10-3-35
10 3 3

<u>Warehouse</u>	Loc Qty	Loc Code	
Location			
Main Warehouse			
ST	1821		
102552	6		
104248	6		
110507	184		
111827	631		8
113422	994		
15924	0		

DART SERVICE INSTRUCTION

TO AMEND DRAWING D350-591 REV. F REF. CANADIAN STC: SH92-6 FAA STC: SH967NE

TO IMPROVE THE FIT OF THE D350-591-311/-312 STEPS, IT IS ACCEPTABLE TO INSTALL THE DSI 9410-011 KIT. INSTALL THE D2732-030 CUSHION (AFT CROSSTUBE) AND D3595-200-300 CUSHION (FWD CROSSTUBE) AS SHOWN IN FIGURE 1 IN PLACE OF THE D2856-400-720 ABRASION STRIP CALLED OUT ON DRAWING D350-591 REV. F.

FOR CUSTOMERS WHO HAVE PREVIOUSLY INSTALLED D2856-400-720 ABRASION STRIPS REMOVE THE ABRASION STRIPS IN ACCORDANCE WITH ICA-D350-591.

PRIOR TO INSTALLING THE DSI 9410-011 KIT.

DSI 9410-011 KITS WILL BE INCLUDED WITH D350-591-311/-312 STEPS AT CHANGE 002 AND SUBSEQUENT.

QTY -041	PART NUMBER	DESCRIPTION
X	DSI 9410-011	STEP MODIFICATION KIT
4	D2732-030	CUSHION
2	D3595-200-300	CUSHION
. 8	AN4-15A	BOLT
16	AN960JD416	WASHER
8	MS21042L4	NUT (OR MS21042-4)

CANADA
DEPARTMENT OF TRANSPORT
AIRCRAFT CERTIFICATION
BRANCH
DAO # 01-O-01


BY: D. SHEPHERD (DE # 02)

DATE: 08.09.08

CERT. NO.: SH92-6

ISSUE NO.: 10

В	SHEET 1 DELETE REVISED P/L. (SEPERATE DSI KIT FROM MAIN KIT SEE NCR 08-082 FOR DETAILS)			AJS	08.09.08
Α	NEW ISSUE			PH	08.03.27
REV.	DESCRIPTION			BY	DATE
DESIGN		AJ5	DART AEROSP	ACE	LTD
DRAWN		AUS	HAWKESBURY, ONTARIO, CANADA		ADA
CHECKE	ED.	_46	DRAWING NO.		REV. B
MFG. AF	PR.	N/A	DSI 9410	\$	SHEET 1 OF 2
APPROV	/ED	140	TITLE		SCALE
DE APPI	₹.	#	STEP MODIFICATION KIT		NTS
DATE	DATE 08.09.08 THIS DOCUMENT IS PRIVATE AND CONTRIBENTIAL AND IS SUPPLED ON THE EXPRESS CONDITION THAT NOT TO BE USED FOR ANY PURPOSE OR CORED OR COMMANCATED TO ANY OTHER PERSON WITHOUT OR BE USED FOR ANY PURPOSE OR CORED OR COMMANCATED TO ANY OTHER PERSON WITHOUT OR PERSON WITHOUT			SS CONDITION THAT IT IS	



BY: D. SHEPHERD (DE #02)

DATE: 08.09.08

CERT. NO.: SH92-6

ISSUE NO.: 10

DESIGN	1/JS	DART AEROSPACE LTD	
DRAWN	AJ 5	HAWKESBURY, ONTARIO,	
CHECKED	, A	DRAWING NO.	REV. B
MFG. APPR.	N/A	DSI 9410	SHEET 2 OF 2
APPROVED	JM	TITLE	SCALE
DE APPR.	-M	STEP MODIFICATION KIT	NTS
08.09.08		COPYRIGHT © 2008 BY DART AEROSPACE LTD THIS COCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR MAY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WITTEN PERMISSION FROM DART AEROSPACE IT.	